

MONUMENT RECORD
State of Indiana - County of Monroe

Section: 33

Township: 9 North


Range: 1 East

Corner ID: BenSo I-21

Monument Description & Remarks: Sandstone with etched notch, length 0.58ft, width 0.23ft, height 1.00ft. Survey Sign 3ft above ground at pt. B

References On File: Darrell Breedlove, Forestry Recovery Tie (1982); Edmund Farkas, M.C.S. Monument Record (1982), on file in Surveyor Office

RECOVERY TIE DRAWING
Field Book 41 Page No. 60




- A - Sandstone with etched notch
- B - S 16° W 0.57' to Survey Sign on metal fence post
- C - S 21° W 5.60' to MAG nail in 16" Pignut Hickory
- D - N 45° E 7.08' to MAG nail in 9" White Oak
- E - S 79° E 16.08' to Face of 6" dead Maple Tree

Not To Scale
Compass Bearing Magnetic North

I, Kevin P. Enright, Monroe County Surveyor, hereby certify that this document was prepared under my direction in accordance with the provisions of section 36-2-12-11 of the Indiana Code; and the above data is given under my hand and seal this 1st day of October, 2008.

Kevin P. Enright



Administered by the Monroe County Surveyor Review Board

Date: 1-13-2009


STATE OF INDIANA - COUNTY OF MONROE

SECTION 32, TOWNSHIP 9N, RANGE 1E

MONUMENT DESCRIPTION & REMARKS

LOCATED AND WITNESSED THE NE SECTIONCORNER STONE

RECOVERY TIE DRAWING



(●) AT CORNER



NOT TO SCALE

STATE OF INDIANA

COUNTY OF MONROE

I, EDMUND O. FARKAS HEREBY CERTIFY THAT THIS DOCUMENT WAS PREPARED UNDER MY DIRECTION IN ACCORDANCE WITH THE PROVISIONS OF SECTION 17-3-64-4 - 17-3-64-8 OF THE INDIANA CODE, BEING ACTS OF 1965, CHAPTER 319; AND THE ABOVE DATA IS GIVEN UNDER MY HAND AND SEAL THIS 5 DAY OF NOV, 19 82 A.D.

SPACE
RESERVED
FOR
RECORDING
OFFICER.

INDIANA REGISTERED LAND SURVEYOR NO. _____

OR _____

UNITED STATES GOVERNMENT AGENCY

TITLE

TOWNSHIP:

BENTON

CORNER I.D.

1-45

SECTION 32, T 9 N, R 1 E

1. On Nov. 5, 1982, the following boundary line work was completed: located & witnessed the NE section corner stone; located and marked the east NS line of NE $\frac{1}{4}$, NE $\frac{1}{4}$ with orange tree marking paint. The stone is described and was witnessed as follows: 2 $\frac{1}{2}$ " X 8" protruding 1' from ground with U-shaped NS notch across top; 5.8' to 7.7" white oak at Az 202°, 7' to 12.3" pignut hickory at Az 42°, 16.1' to 4.2" sugar maple with fence wire attached at Az 98°. No steel stake was driven next to the stone. One boundary line sign was nailed to the 7.7" white oak in a NS orientation.

Darrell Breedlove, Timber Specialist

2. Note: map not drawn when info. recorded

David Vadas, Timber Specialist
12/15/84

3. On September 13, 1988 I repainted and reposted the boundary line run on Nov. 5, 1982 which included the following: E line of the NE $\frac{1}{4}$, NE $\frac{1}{4}$, Sec. 32. Additional boundary signs were placed along the line and additional trees were painted to make the line more visible. Signs were placed on ridgetops and bottoms of ravines or along every 220 feet of line or so. The Stone at the NE section corner was still present. A sign was placed along the S line at the turning corner of the SE corner of the NE $\frac{1}{4}$, NE $\frac{1}{4}$, Sec. 32.

David Vadas, Timber Specialist

4. On February 14, 1990 Marty Calvert, Asst Property manager, and I set SFP at the following corners: The NW, NE, & SE corners of the NE $\frac{1}{4}$, NE $\frac{1}{4}$ of this section. The NW corner was set according to an old fence corner intersection. This corner is suspect as there was a pinched pipe and a rebar further along the line to the west. However, the fence corner fits the topomap well and also a treeline heading west and an old fence line (buried) heading east. The fence to the south also lines up with this fence corner. The NE corner was a good looking stone with a prominent notch in it. The SE corner is vague and was set to approximate the intersection of 3 old fences running N, E, and W and also a tree line heading south.

David C. Vadas, Timber Specialist



10/01/2008

Ben So I-21